Submit 3 Copies To Appropriate District State of New Me	
Office Energy, Minerals and Natu	
1625 N. French Dr., Hobbs, NM 87240	WELL API NO.
District II 1301 W. Grand Ave. Artesia NM 88210 OIL CONSERVATIO	N DIVISION 30-025-38488
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV OIL CONSERVATION OIL CONSERVATION OIL CONSERVATION Santa Fe, NM 8	nncis Dr. 5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 FEB 10 Language Santa Fe, NM 8	7505 STATE FEE 🗷
District III 1000 Rio Brazos Rd., Aztec, NM 87410 FEB 10 20220 South St. Fra District IV 1220 S. St. Francis Dr., Santa Fe, NM 8740 BBSOCD SUNDRY NOTICES AND REPORTS ON WE	6. State Oil & Gas Lease No.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN ODIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-10)	OR PLUG BACK TO A SHERMAN 13 FEE
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well X Gas Well Other DRY	#003
2. Name of Operator	9. OGRID Number
CIMAREX ENERGY CO. OF COLORADO ATTN: ZE	
3. Address of Operator	10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	DENION; WOLFCAMP
4. Well Location	
Unit Letter A: 430 feet from the NO	RTH line and 430 feet from the EAST line
Section 13 Township 15S	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,776' - GR	
Pit or Below-grade Tank Application or Closure	
Pit type STEEL Depth to Groundwater Distance from nearest free	sh water well* Distance from nearest surface water*
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material * NONE WITHIN 1,000'	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TENTONIA NEMEDIAE WORK	THE MEDIAL WORK
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB
CONDITIONS OF PA APPROVAL: Approved as to	OTHER: WELL PLUGGED AND ABANDONED 02/07/11.
plugging of the Well Bore. Liability under bond is retained until surface restoration is completed to all pertinent details, and give pertinent dates, including estimated date	
retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection". Multiple Completions: Attach wellbore diagram of proposed completion	
02/01/11: ROTARY WIRELINE SET 5-1/2" CIBP @ 9,150'.	
02/05/11: RIH W/ TBG. TO 9,150' X CIRC. WELL W/ PXA MUD; PUMP A 25 SX. CMT. PLUG @ 9,150'-8,950'(CALC.); PUMP A 25 SX. CMT. PLUG @ 7,686'-7,486'(CALC.); PUMP A 25 SX. CMT. PLUG @ 6,856'-6,656'(CALC.).	
02/06/11: FUMP A 25 SX. OMT. PLUG @ 4,585'; WOC X TAG TOP OF OMT. PLUG @ 4,371'; PUMP A 25 SX. OMT. PLUG	
@ 3,267'-3,067'(CALC.); PUMP A 25 SX. CMT	
	SX. OMT. PLUG @ 1,950'; WOC X TAG OMT. PLUG @ 1,827';
); CIRCULATE TO SURFACE A 25 SX. CMT. PLUG @ 63'-3;
DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELL	ON STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARKER.
I hereby certify that the information above is true and complete to the grade tank has been with he constructed or closed according to NMOCD guideling.	e best of my knowledge and belief. I further certify that any pit or belowes X, a general permit or an (attached) alternative OCD-approved plan
SIGNATURE TIT	
	nail address: deyler@milagro-res.com Telephone No. (432) 687-3033
For State Use Only	
APPROVED BY	TLE STATE MGZ DATE 2-14-2011
Conditions of Approval, if any:	