New Mexico Oil Conservation Division, District I 1625 N. French Drive

Hobbs, NM 88240

Form 3160-5 . (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT				5. Lease Serial No.	
SUNDRY	NOTICES AND REP		NMNM0155494A		
	form for proposals	6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name		
abandoned well.	Use Form 3160-3 (A	(PD) for such propo	osals.		
SUBM	IT IN TRIPLICATE – Othe	7. If Unit of CA/A ₁	7. If Unit of CA/Agreement, Name and/or No. Cato San Andres Unit		
1. Type of Well		Cato San Andres			
Oil Well Gas	Well Other	8. Well Name and I Cato San Andres	8. Well Name and No. Cato San Andres Unit #175		
Name of Operator Cano Peto of New Mexico, Inc.			9. API Well No. 30-005-20189		
3a. Address 801 Cherry Street Suite 3200 Unit 25 Fort Worth, TX 76102		3b. Phone No. (include are		10. Field and Pool or Exploratory Area	
		817-698-0900	i i	Cato; San Andres	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. Country or Pari	sh, State	
F-32-08S-30E 1980 FNL 1980 FWL		Chaves Co, NM			
12. CHE	CK THE APPROPRIATE BO	X(ES) TO INDICATE NAT	TURE OF NOTICE, REPORT OR OT	THER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
✓ Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
_	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	Other tag bottom	
	Change Plans	Plug and Abandon			
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	ork and approximate duration thereof. If	
following completion of the invol-	work will be performed or proved operations. If the operation Abandonment Notices must be	ovide the Bond No. on file was on results in a multiple comp	and measured and true vertical depth ith BLM/BIA. Required subsequent i pletion or recompletion in a new interv ments, including reclamation, have be	reports must be filed within 30 days	
BLM ORDER NO. 24-003-10W MIRU pulling unit. RIH w/ sinker bar on the end of san production.	d line to check depth. Res	ults of data obtained from	this procedure will determine whe	ether this well can be returned to	
RD and move to next w					
			RECEIVED		
			JUL 28 2010	JUL 28 2010	
			HOBBSOCD		
4. I hereby certify that the foregoing is to	rue and correct. Name (Printed	(Typed)			
Collin Strawn			Title Engineer		
Signature Colle Str	~	Date 06/14	4/2010		

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

PETROLEUM ENGINEER

JUL 2 1 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereof

Office

ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Pecos District Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201-2019 www.nm.blm.gov



In Reply Refer To: NM-82050X 3160 (P0130)

CERTIFIED-RETURN RECEIPT REQUESTED 7000 0520 0023 4992 4731

Cano Petroleum of New Mexico, Inc. 801 Cherry Street, Suite 3200 Fort Worth, TX 76102

JUL 2 2 2010

RECEIVED

JUL 28 2010 HOBBSOCD

Gentlemen:

The Bureau of Land Management (BLM) received Sundry Notices of Intent Form 3160-5 on June 18, 2010 for Cato Unit Wells Numbers 12, 15, 34, 62, 66, 117, 132, 134, 138, 140, 151, 152, 153, 160, 161, 164, 165, 166, 171, 172, 174, 175, 177, 178, 179, 181, and 184 in response to Written Order Number 24-002-10W (enclosed). The subject Sundry Notices state Cano's plans to run in hole with sinker bar on the end of sand line to check depth to determine which well(s) can returned to production is not considered a sufficient plan in response to Written Order Number 24-002-10W. The subject Sundry Notices are being returned to you Denied. These Sundry Notices also refer to an incorrect Written Order Number 24-003-10W. BLM is requiring Cano provide a more detailed plan to return the subject well(s) to continuous production or plug the well(s) with a plugging program approved by this BLM office within 60 days from receipt of this letter.

If you need additional information and/or have any questions regarding this letter, please contact David Glass, Petroleum Engineer at the above address or at (575) 627-0275.

Sincerely,

15/ Angel Mayes

Angel Mayes Assistant Field Manager, Lands and Minerals

cc: NM (P0130, File Room) Well Files