



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**Susana Martinez**  
Governor

**John H. Bemis**  
Cabinet Secretary

**Daniel Sanchez**  
Acting Division Director  
Oil Conservation Division

**\*Response Required – Deadline Enclosed\***

*Underground Injection Control Program*

*"Protecting Our Underground Sources of Drinking Water"*

15-Mar-11

**CONOCOPHILLIPS COMPANY**

3300 N A STREET BLDG 6 #247

MIDLAND TX 79710-0000

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE**  
**Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.


Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

**MECHANICAL INTEGRITY TEST DETAIL SECTION**

<b>MCA UNIT No.084</b>			<b>30-025-00639-00-00</b>	
			P-22-17S-32E	
			Active Injection - (All Types)	
Test Date:	3/10/2011	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result: F	Repair Due:	6/13/2011
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Casing	FAIL CAUSE:	
Comments on MIT: ANNUAL IMIT (PRESSURE TEST) FAILED. MGB.				
<b>MCA UNIT No.123</b>			<b>30-025-00705-00-00</b>	
			D-26-17S-32E	
			Active Injection - (All Types)	
Test Date:	3/10/2011	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result: F	Repair Due:	6/13/2011
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Communication Between	FAIL CAUSE:	
Comments on MIT: ANNUAL IMIT (PRESSURE TEST) FAILED. MGB.				
<b>MCA UNIT No.273</b>			<b>30-025-23730-00-00</b>	
			L-26-17S-32E	
			Active Injection - (All Types)	
Test Date:	3/10/2011	Permitted Injection PSI:	Actual PSI:	
Test Reason:	Annual IMIT	Test Result: F	Repair Due:	6/13/2011
Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Communication Between	FAIL CAUSE:	
Comments on MIT: MIT FAILED. MGB.				

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




**COMPLIANCE OFFICER**

Hobbs OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. \* Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

**EMNRD  
OIL CONSERVATION DIVISION  
1625 N FRENCH DRIVE  
HOBBS NM 88240**



HASLER	015H14150977	US POSTAGE
	<b>\$0.44</b>	
	03/15/11	
	Mailed From 88240	

**CONOCOPHILLIPS COMPANY  
3300 N A STREET BLDG 6 #247  
MIDLAND TX 79710**