RECEIVED

MAR 2 2 2011

Submit One Copy To Appropriate District Office HOBBSOCD State of New Mexico Office Minorals and Natural Branch and Natural Bra	Form C-103
District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	January 20, 2011 WELL API NO.
District II	30-025-10638
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd Aztec NM 87410	STATE FEE Z
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Skelly Penrose B Unit
PROPOSALS.)	
1. Type of Well: Oil Well Gas Well Other PA'd Injection Well	8. Well Number 18
2. Name of Operator	9. OGRID Number
Providence Energy Services, Inc. dba Kelton Operating	012444
3. Address of Operator P.O. Box 928 Andrews, Texas 79714-0928	10. Pool name or Wildcat
4. Well Location	Langlie Mattix 7 Rvrs QN Grbg
	/
Unit Letter A: 660 feet from the North line and 660 feet from the East line	\checkmark
Section 5 Township 23 S Range 37 E NMPM Lea County NM	Control of the Contro
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON	
PULL OR ALTER CASING	JOB 🔲
OTHER:	
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
TERMANENTET STAMTED ON THE MARKER S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	var (x carea onsite concrete bases do not have
All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC.	All fluids have been removed from non-
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service	
company equipment, has been removed from lease and well location.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
	and an inspection.
O V M	
SIGNATURE TITLE President	DATE <u>03/21/2011</u>
TYPE OR PRINT NAME <u>Dale Kelton</u> E-MAIL: providenceenergy	@guddonlink not DUONE 400 (C) 100
For State Use Only	@suddenlink.net PHONE: 432-661-1364
	ACC - 1 1
APPROVED BY: Wash Winfarm TITLE Compliance	Officer DATE 3/23/2011
Conditions of Approval (if any):	