Submit One Copy To Appropriate District Office District I  State of New Mexico State of New Mexico Minerals and Natural Resources	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 2 2011 CONCEDVATION DIVISION	30-025-10677
District III 1000 Rio Brazos Rd., Aztec, NM 874100BBSUCI220 South St. Francis Dr. District IV  Santa Fe, NM 87505	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 OBBS Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	o. State on & das Lease No.
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Skelly Penrose B Unit
1. Type of Well: Oil Well Gas Well Other PA'd Injection Well	8. Well Number 59
2. Name of Operator	9. OGRID Number
Providence Energy Services, Inc. dba Kelton Operating  3. Address of Operator	10. Pool name or Wildcat
P.O. Box 928 Andrews, Texas 79714-0928	Langlie Mattix 7 Rvrs QN Grbg
4. Well Location	
Unit Letter P: 330 feet from the South line and 330 feet from the East li	ne
Section 8 Township 23 S Range 37 E NMPM Lea County NM	
11. Elevation (Show whether DR, RKB, RT, GR,	etc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Oth	ner Data
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SUBSEQUENT REPORT OF:  NORK
	E DRILLING OPNS. P AND A
PULL OR ALTER CASING  MULTIPLE COMPL  CASING/CE	<del></del>
OTHER:	Operator's pit permit and closure plan
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
∇/ T	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed.	removed. (Poured onsite concrete bases do not have
to be removed.)	
<ul> <li>✓ All other environmental concerns have been addressed as per OCD rules.</li> <li>✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-</li> </ul>	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service	
company equipment, has been removed from lease and well location.	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE President	DATE <u>03/21/2011</u>
TYPE OR PRINT NAME Dale Kelton E-MAIL: providencee	nergy@suddenlink.net PHONE: 432-661-1364
For State Use Only	
APPROVED BY: Want Cetylore TITLE COMPIENCE	e Officer DATE 3/29/11
Conditions of Approval (if any):	DATE STETTIT