

070336

(SUBMIT IN TRIPPLICATE)


Land Office

Lease No.

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

ARTESIA OFFICE COPY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	X	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 1

1957

Well No. 1 is located 660 ft. from N line and 1980 ft. from E line of sec. 1
NE of Section 1 14S 31 E N.M.P.M.
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Caprock - Green Chaves New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4402 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Amended plans are to leave approximately 600' of 5 1/2" casing in hole, to put a 10 sack plug at the shoe (3077'), a 15 sack plug at base of salt, a 15 sack plug at the top of the salt, fill hole with mud and leave surface pipe in place.

Called 2-5-57 Jap. P.A. as above

Sundry Notice from Rec'd today on 53-3077-10000

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Landa Oil Company

Company

5738 North Central Expressway

Address

Dallas 6, Texas

By

John W. McCarthy

Title

Geologist