

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

HOBS OCD  
APR 25 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-041-20821
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other WIW <input type="checkbox"/>		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator EOR Operating Company		6. State Oil & Gas Lease No. 306451
3. Address of Operator 200 N. Loraine Suite 1440 Midland, TX.79701		7. Lease Name or Unit Agreement Name Horton Federal
4. Well Location Unit Letter H-1700 feet from the N line and 920 feet from the E line Section 30 Township 08S Range 35E NMPM County Roosevelt		8. Well Number 38 WIW
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 257420
		10. Pool name or Wildcat 46930 - San Andres

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☒

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well had casing leak @ 2228' in 5 1/2" casing  
Perforated @ 2288' / pumped 50 sacks class c cement @ 1 b/m @ 1600 psi / drilled out from 2208' to 2305'  
Set new 2 3/8 X 5 1/2 Arrow Set pkr @ 4560' / tested backside @ 500 psi for 30 minutes - good chart  
Request OCD/HFO representative to witness Material Integrity Test on 4/28/2011  
(8 5/8 - 412' / 5 1/2 - 4805' / Perfs - 4660' - 4740' / TD - 4805' / PBTD - 4756')

Spud Date:

11/11/1987

Rig Release Date:

12/14/1987

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Andy Chalker TITLE Operations Manager DATE 4/21/2011

Type or print name Andy Chalker E-mail address: andy.chalker@att.net PHONE: 432.687.0303  
For State Use Only

APPROVED BY: [Signature] TITLE PETROLEUM ENGINEER DATE APR 26 2011  
Conditions of Approval (if any):