## HOBBS OCD

Form 3160-5 (August 2007

## New Mexico Oil Conservation Division, District I 1625 N. French Drive

**UNITED STATES** 

MAY 1 1 2011 DEPARTMENT OF THE INTERIOR DES. NM 88240

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

**BUREAU OF LAND MANAGEMENT** 

NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NM0558287 6. If Indian, Allottee or Tribe Name

Do not use this f abandoned well.	form for proposals : Use Form 3160-3 ( <i>F</i>	to drill or to re-e \PD) for such pr	nter an oposals.			
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well  Oil Well  Gas W	Vell Other	/		8. Well Name and No. Morgan A Federal #4	4 /	
2. Name of Operator Ridgeway Arizona Oil Corporation				9. API Well No. 30-041-10415	4,	
3a. Address 3b. Phone No.			de area code)	10. Field and Pool or E		
200 N. Loraine, Suite 1440, Midland TX. 79701 432.687.030				Chaveroo-San Andres		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. Country or Parish, State		
K-27-07S-33E 1980 FSL 1980 FWL		Roosevelt Co. NM				
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICATE	E NATURE OF NOTION	CE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION TYPE OF AC				ITION		
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Tre		luction (Start/Resume) amation	☐ Water Shut-Off ☑ Well Integrity	
Subsequent Report	Casing Repair	New Constru	uction Rec	complete Other		
Bassequent report	Change Plans	Plug and Ab	andon Tem	porarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Wat	Water Disposal		
ENDING MAY 27 20	prefinal inspection.)  preprint  fill - clean out as needed  fill - to test casing integrity  erform cement squeeze/d  w/tubing/packer - circulate  500 - perfs-4191-4306 - T	irill out e packer fluid TD @ 4426) Secon NM-0: 1-Mor Quant Will T Is Not	nd Run Ticket Fo 558287 Was Due gan B Federal C tities After NOV	or Load Of Oil Fro MAR 02 2011! W eased Production 201 <b>0</b> ↓ Lease NM-0 uction In Paying O	om Lease Vell No. In Paying 0558287	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)						
Andy Chalker			Title Operations Manager			
Signature John Cha W—			Date 04/08/2011			
ACCEPTED	OR REHISEBACE	FOR FEDERAL	OR STATE OF	FICE USE		
Approved by /S/DAVIDR. GLASS Conditions of approval, if any, Approved by Approved this notice does not warrant or or			Title		Date	
that the applicant holds legal or equitable entitle the applicant to conduct operations	title to those rights in the subj	ect lease which would	Office			
Title 18 U.S.C. Section 1001 and Title 143	RU.SC.ASC.56on 1212, make it			to make to any departmen	nt or agency of the United States any false	
fictitious or fraudulent statement (Instructions on page 2)	weint Work Nistic Iron matter w	vithin its jurisdiction	HOATTACH			
(mandenons on page 4)		A A Ni II good in some			,	

## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, call (575) 420-2832 or after office hours call (575) 627-0205.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)