## New Mexico Oil Conservation Division, District I

Form 3160-5 (August 2007)

**UNITED STATES** 

1625 N. French Drive

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

50-5 <b>(30</b>		tton		UN	ITED	STA	ΓES	1	025	N.	Fren	ch	Dri	V
2007)	11	SOU BUR BUR	PAR	TME	NT O	F TH	E INTE	RIC	Hol	bbs,	NM.	88	3240	ì
YABA	F	BÜR	REA	U OF	LAN	D MA	NAGE	ME	NT	•				

5. Lease Serial No.

Mi.					NM0558287					
	OTICES AND REPO			<b>n</b>	6. If Indian, Allottee or	Tribe Name				
	Use Form 3160-3 (A									
SUBMI	TIN TRIPLICATE – Other	7. If Unit of CA/Agreement, Name and/or No.								
1. Type of Well										
Oil Well Gas W	VellOther				8. Well Name and No. Morgan B Federal #4	4				
2. Name of Operator Ridgeway Arizona Oil Corporation	/				9. API Well No. 30-041-10456					
3a. Address		3b. Phone No.	(include area co	ode)	10. Field and Pool or E	/				
200 N. Loraine, Suite 1440, Midland TX. 79701	432.687.0303	Chaveroo-San Andres			es /					
4. Location of Well (Footage, Sec., T.,	R.,M., or Survey Description	1)			11. Country or Parish, State					
D-26-07S-33E 660 FNL 660 FWL				Roosevelt Co. NM						
12. CHEC	K THE APPROPRIATE BO	OX(ES) TO IND	CATE NATUR	E OF NOTIO	CE, REPORT OR OTHE	ER DATA				
TYPE OF SUBMISSION	TYPE OF SUBMISSION				TYPE OF ACTION					
✓ Notice of Intent	Acidize	Deepe	n .	Prod	uction (Start/Resume)	Water Shut-Off				
The state of America	Alter Casing	Fractu	ire Treat	Recla	amation	✓ Well Integrity				
Subsequent Report	Casing Repair	New (	Construction	Reco	mplete	Other				
Subsequent report	Change Plans	Plug a	and Abandon	_ ] Temp	oorarily Abandon					
Final Abandonment Notice	Plug Back Wa			ter Disposal						
determined that the site is ready for MIRU PU/POOH w/all downhole equ RIH w/bit-scraper/tag PBTD (4747') RIH w/RBP/tbg - set RBP@4029' (p POOH w/tbg/RU pump truck to test IF well does not test - RIH w/4 1/2 pl fino casing leak is found, RIH w/tub (8 5/8,@356 / 4 1/2, @ 4747-TD)  ACCEPTED APPROVED FOR MAY 27	uipment erfs - 4134-4361) for MI kr to sopt leak/Set CIBP/s ing/pull RBP/RIH w/CIBP		Second F NM-0558 1-Morgar Quantitie Will Term	M to witness Run Ticke 287 Was I n B Feder s After No	t For Load Of Oil to Due MAR 02 2011 al Ceased Production In Paying By MAY 27 2011!	! Well No. ction In Paying ⋈M-0558287 ng Quantities				
14. I hereby certify that the foregoing is tr	no and correct. Name (Print	1/T 1\								
, , ,	as and correct. Ivalle (17thte	.u. 1 ypcu)								
Andy Chalker		Title Operations Manager								
Signature May Cha	M		Date 03/21/2	011						
ACCEPTED FOR F	RECOTHIS SPACE	FOR FEDE	RAL OR ST	ATE OF	ICE USE					
Approved by S/DAVID  APR 1 9 20  Conditions of approval, if any, are attached that the applicant holds legal or equitable ti	R. GLASS  Approval of this notice doe	s not warrant or ce	Title ertify		D	)ate				
mai me applicant noids legal or equitable ti	tie to those rights in the subje	ct lease which wo	uld Office							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and will fully to make to any department or agency of the United States any false, fictitious or-fraudulent statements or representations as to any matter within its jurisdiction.

## BUREAU OF LAND MANAGEMENT Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

## Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, call (575) 420-2832 or after office hours call (575) 627-0205.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)