NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

	(2	Submit to approp	riate Distri	ict Offic	e as p	er Com	mi≋sion Rul	• 1106)			
Name of Company Robert A. Dean Address %V. Pickett, 901 Midland Saving Bldg., Midland. Texas										nd Savings	
Lease M	achris-Sta	te	Well No.	Unit L	etter D	Section 20	Township	10 - s	Range	32-E	
Date 2013 Per 1920 Pool Undesignated					County						
THIS IS A REPORT OF: (Check appropriate block)											
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):											
Plugging Remedial Work											
Detailed account of work done, nature and quantity of materials used, and results obtained.											
Well plugged and abandoned, plugs as follows: 25 sacks cement at total depth of 2982'; 25 sacks at 2000'; 25 sacks at 1200'; 25 sacks at 395'; 10 sacks in top with proper New Mexico marker installed. Pits leveled, and junk removed. Location cleaned up ready for inspection. Heavy mud between all plugs. 395' 8-5/8" casing left in hole.											
Witnessed by Robert A. Dean Position Operator Company Robert A. Dean											
to be an area of the beautiful and the beautiful											
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA											
D F Elev. T D			PBT	PBTD			Producing Interval Complete			npletion Date	
Tubing Diameter Tubing Depth		<u>.</u>	Oil String Diam		g Diame	ter Oil String Depth			h		
Perforated Interv	al(s)	. 		·····							
Open Hole Interval						Producing Formation(s)					
RESULTS OF WORKOYER											
Test	Date of Oil Production BPD			Producti 4CFPD			Production BPD	GOR Cubic feet		Gas Well Potential MCFPD	
Before Workover									· .		
After Workover											
OIL CONSERVATION COMMISSION					I hereby certify that the information given above is true and complete to the best of my knowledge.						
rester I Cement					Name						
Title					Position Agent						
Date					Robert A. Dean						