

**NEW MEXICO OIL CONSERVATION COMMISSION**  
**Santa Fe, New Mexico**

**MISCELLANEOUS REPORTS ON WELLS**

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

**Indicate Nature of Report by Checking Below**

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	<b>X</b>	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

August 6, 1959

(Date)

Hobbs, New Mexico

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

McELROY RANCH COMPANY

(Company or Operator)

LEA STATE "BT"

(Lease)

Hobbs Pipe & Supply Company

(Contractor)

Well No. 1 in the SE  $\frac{1}{4}$  SW  $\frac{1}{4}$  of Sec. 22

T. 10-S, R. 32-E, NMPM, Mescalero (Penn.) Pool, Lea County.

The Dates of this work were as follows: July 29, 1959 through August 5, 1959

Notice of intention to do the work (was) (~~not~~) submitted on Form C-102 on July 15, 1959,  
 (Cross out incorrect words)

and approval of the proposed plan (was) (~~not~~) obtained.

**DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED**

5½" casing collapsed at approximately 7400'. 9-5/8" casing was set at 3452' and cemented with 2500 sxs. Cement was behind 5½" casing to approximately 2750', which tied approximately 700' of the 5½" and 9-5/8" together. Could not load hole with perforations in the 5½" casing open. Set Baker Cast Iron Bridge Plug at 4100' with approximately 8' of cement on top of bridge plug. Shot 5½" casing off at 2732'. Loaded hole with 10# mud. Spotted 30 sxs at 2782' - 2672'. Shot 9-5/8" casing off at 810'. Spotted 30 sxs at 835' - 785'. 45 sxs at 404' - 349' or base of surface pipe, 15 sxs at 18' - 0'. Steel plate was welded on top of surface with permanent location marker attached.

Location has been cleaned and levelled and all pits filled as required by Commission. Well Record was submitted at time of completion of well.

Witnessed by [Signature] McElroy Ranch Company Ass't. Production Supt.  
 (Name) (Company) (Title)

Approved: [Signature]  
 OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name [Signature]

Position Division Manager

Representing McElroy Ranch Company

Address 703 Wilco Bldg., Midland, Texas

(Title)

(Date)