

The Texas Company

State of New Mexico "BR" #1

Drill Stem Test:

- DST NO. 1: 8115-8303. Tool open 1 hour and 7 minutes. Recovered 210' distelate and 90' heavy distelate cut drilling mud.
- DST NO. 2: 8300-8429. Tool open 2 hours. Recovered 1920' fluid and 400' drilling mud cut with distelate and salt water.
- DST NO. 3: 8550-8615. Tool open 1 hour. Recovered 108' drilling mud.
- DST NO. 4: 9165-9421. Tool open 2 hours. Recovered 720' gas cut drilling mud.
- DST NO. 5: 9722-9783. Packer failed.
- DST NO. 6: 9707-9790. Tool open 2 hours. Recovered 570' heavy gas cut drilling mud.
- DST NO. 7: 10550-10600. Tool open 3 hours. Recovered 2116' oil cut mud.

I am going well to date.

YACOBUS, 24141 5th

DLIT 05-01 11170

Time	Location	Remarks
11:00	1000-1000	1000-1000
10:00	1000-1000	1000-1000
9:00	1000-1000	1000-1000
8:00	1000-1000	1000-1000
7:00	1000-1000	1000-1000
6:00	1000-1000	1000-1000
5:00	1000-1000	1000-1000
4:00	1000-1000	1000-1000
3:00	1000-1000	1000-1000
2:00	1000-1000	1000-1000
1:00	1000-1000	1000-1000
0:00	1000-1000	1000-1000