

DUPLICATE


JAKE L. HAMON - L. H. CHAMBERS #2



Sec. 1, T-12-S, R-32-E, East Caprock-Wolfcamp Field, Lea County, New Mexico

DRILLSTEM TESTS

Test #1 - 8444-30', open 2 hrs 45 min, fair blow for 1 hr, decreasing to very weak. Recovered 30' drilling mud, BHP Off, SIP Off, HP 4650#, 6-15-53.

Test #2 - 8505-74', open 1 hr 21 min, immediate weak blow picked up to fair blow in 17 min, decreased to very weak, increased to strong blow in 1 hr 3 min, decreased to bubbles in 1 hr 11 min, died in 1 hr 14 min, re-opened tool in 1 hr 21 min to see if it was plugged. Tool was open. Shut in immediately. Recovered 45' drilling mud, BHP Off, SIP Off, HP 5625#, 6-17-53.





RECEIVED

RECEIVED

RECEIVED

RECEIVED

RECEIVED