


OIL CONSERVATION COMMISSION

Santa Fe, New Mexico



DUPLICATE MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<input checked="" type="checkbox"/>		

March 3, 1948

Monument, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____
Amerada Petroleum Corporation **State SCB** Well No. **1** in the _____
 _____ Company or Operator _____ Lease _____
SE 1/4 NE 1/4 of Sec. **5**, T. **12S**, R. **32E**, N. M. P. M.,
Caprock Field, **Lea** County.

The dates of this work were as follows: **March 2, 3, 1948**

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on **March 2,** 19**48**
 and approval of the proposed plan was (~~obtained~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

3080' Total Depth, Anhydrite & Salt. Ran Schlumberger Survey. Spotted 10 sacks of cement from 3080' to 3024' at 2:30PM, 3-3-48. Spotted 10 sacks of cement from 252' to 233' at 4:30PM, 3-3-48. Put plug in top of 10-3/4" surface pipe with 10 sacks of cement with 4" pipe 5' high in center. Finished and released rig at 6:30PM, 3-3-48.

Witnessed by **C. E. Telge** **Amerada Petroleum Corporation** **Farm Boss**
 _____ Name _____ Company _____ Title _____

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

3rd. day of **March**, 19**48**

Name **W. H. Taylor**

Position **Asst. Dist. Supt.**

Representing **Amerada Petroleum Corporation**
 _____ Company or Operator _____

My commission expires **May 9, 1949**

Address **Drawer D, Monument, New Mexico**

Remarks:

APPROVED
MAR 8 1948

Date _____

Ray Garbrough
 _____ Name _____
OIL & GAS INSPECTOR