MISCELLANEC	US REPORTS ON WELLS	
		n a naga a paga Sangar Sangar Sangar Sangar
is completed. It should be signed and filed as a report of casing shut off, result of plugging of well, and oth	tion Commission District Office within ten days the pho- on beginning drilling operations, results of shooting we her important operations, even though the work was s in the Rules and Regulations of the Commission.	R results of test
-	re of report by checking below.	
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON REPAIRING WELL	بەرەرىيى
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL	REPORT ON PULLING OR OTHERWI ALTERING CASING	ISE
REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON DEEPENING WELL	
SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL	X	
SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL May 2: Following is a report on the work done and the results	X 3, 1952 Date Midland, Texa: F s obtained under the heading noted above at the	
SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL May 2: Following is a report on the work done and the result: The l'exes Company State of !	X 	in the
SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL May 2: Following is a report on the work done and the result: The l'exes Company State of !	X 	in the
SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL May 2: Following is a report on the work done and the results The l'exes Company of Operator SW4 NE4 of Sec. (Mildeat Pool	X 3, 1952 Date Midland, Texa: P s obtained under the heading noted above at the ew Mexico_Lease DB Well No. 1 5,, T. 12-S R. 32=E Lea	in the , N. M. P. M., County.
SHUT-OFF REPORT ON RESULT OF PLUGGING OF WELL May 2: Following is a report on the work done and the results The I'exes Company of Operator SW4 NE4 Mildeat Pool	X 3, 1952 Date Midland, Texa: F s obtained under the heading noted above at the ew Mexico BD ⁿ Well No	in the , N. M. P. M., County.

Well was drilled to a total depth of 1424' without encountering oil or gas in commercial quantities; therefore, on 4-1-52 well was abandoned, salvaged, and plugged in the following manner: using heavy mud between cement plugs, spotted 20 sacks in 13 3/8 casing set at 350', 15 sacks in top of 13 3/8" casing. All 13 3/8" casing left in hole

Witnessed byName	Company	Title
APPROVED: OIL CONSERVATION COMMISSION Mini Multiply 72 Title Date	I hereby swear or affirm that is true and correct. Name Position Asst Dist. S Representing Address Box 1270, M	upt. ass. Company