

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	X	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	Sandfrac

December 29, 1954

(Date)

Midland, Texas

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

M. A. MACERIS

(Company or Operator)

State

(Lease)

Brantly Drilling Company, Inc.

(Contractor)

Well No. **34-8**

in the **SW** $\frac{1}{4}$ **SE** $\frac{1}{4}$ of Sec. **8**

T. **12-S**, R. **32-E**, NMPM., **North Caprock Queens** Pool, **Lea** County.

The Dates of this work were as follows: **12-18 thru 12-29-54**

Notice of intention to do the work ~~was~~ (was not) submitted on Form C-102 on _____, 19____,

(Cross out incorrect words)

and approval of the proposed plan ~~was~~ (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

12-18 Ran 5½" 14# casing at 2978 and cemented w/ 75 sxs.
 12-20 Tested casing w/ 1000 psi before drilling plug - o.k.
 Blew hole dry w/ air and drilled plug - no fluid entry.
 12-21 Drilled to T.D. 3015'
 12-23 Treated open hole w/ 10,000 gal sandfrac - breakdown pressure 2850#
 12-26 Swabbed well dry after recovery ± 150 bbls. oil. No new oil, no more fluid in hole.
 12-29 No fillup of fluid - preparing to plug
 1-1-55 Set 10 sxs. plug from T.D. to 2930'. Shot csg. off at 2155' and pulled same
 1-2-55 Set 10 sx. plug on top of 5½" at 2155 and 10 sxs. at 1500, 300 and surface w/ 4' of 4" above C.L.

Verbal permission to plug was received from L. A. Hanson on 12-30-54.

Witnessed by **R. J. Paxton**
 (Name)

M. A. MACERIS
 (Company)

Geologist
 (Title)

Approved: **OIL CONSERVATION COMMISSION**

M. L. Armstrong
 (Name)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name **R. J. Paxton**

Position **Geologist**

Representing **M. A. MACERIS**

Address **811 Midland Tower Bldg., Midland, Texas**

(Title)

(Date)