

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1106)

Company Sunray Mid-Continent Oil Company Box 128, Hobbs, New Mexico
(Address)
Lease New Mexico State B Well No. 4 Unit L S 16 T 12-S R 34-E
Date work performed 7-6-55 POOL North Caprock-union

This is a Report of (Check appropriate block) ☒ Result of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Drilled 11" hole to 1420'. Top Anhydrite at 1410'. Set 8 5/8" OD 24# J55 Casing with Texas Pattern Shoe on Anhydrite shoulder at 1420'. Placed oil emulsion mud around and behind 8 5/8" casing. Casing was tested by boiling hole dry. Converted to cable tools at this point.

After 5 1/2" oil string is set and cemented, the 8 5/8" casing will be pulled.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl. Date _____
Tbng. Dia. _____ Tbng. Depth _____ Oil String Dia _____ Oil String Depth _____
Perf. Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

Oil Conservation Commission

Name

Title

Date

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Company

J. A. Parry
Hobbs Area Superintendent

Sunray Mid-Continent Oil Company

