



## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1105) APR 10 1967

Name of Company <b>Morris R. Antweil</b>				Address <b>P. O. Box 1058, Hobbs, New Mexico</b>			
Lease <b>State "C"</b>		Well No. <b>1</b>	Unit Letter <b>J</b>	Section <b>20</b>	Township <b>12S</b>	Range <b>32E</b>	
Date Work Performed		Pool <b>Caprock Queen</b>			County <b>Lea</b>		
THIS IS A REPORT OF: (Check appropriate block)							
<input type="checkbox"/> Beginning Drilling Operations <input type="checkbox"/> Casing Test and Cement Job <input checked="" type="checkbox"/> Other (Explain):							
<input type="checkbox"/> Plugging <input type="checkbox"/> Remedial Work							
Detailed account of work done, nature and quantity of materials used, and results obtained.  <b>We wish to continue the status of this well as Temporarily Abandoned, pending waterflood operation in the immediate area. The Northeast Caprock Queen Unit, operated by Texaco, is in the formative stages, and offsets this lease.</b>							
Witnessed by		Position		Company			
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY							
ORIGINAL WELL DATA							
D F Elev.		T D		P BTD		Producing Interval	
Completion Date							
Tubing Diameter		Tubing Depth		Oil String Diameter		Oil String Depth	
Perforated Interval(s)							
Open Hole Interval				Producing Formation(s)			
RESULTS OF WORKOVER							
Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD	
Before Workover							
After Workover							
OIL CONSERVATION COMMISSION				I hereby certify that the information given above is true and complete to the best of my knowledge.			
Approved by 				Name  <b>Burton Veteto</b>			
Title				Position <b>Agent</b>			
Date				Company <b>Morris R. Antweil</b>			