

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS	☒	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	☒	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

11-8-54

Midland

(Date)

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

M. A. MACHRIS

State 12-32

(Company or Operator)

(Lease)

Brantly Drilling Company

Well No. 32-20

SW

NE

20

(Contractor)

1/4

1/4

of Sec.

T. 12N

R. 32E

East Caprock Queens

Lea

NMPM,

Pool,

County.

10-26 through 11-8-1954

The Dates of this work were as follows:

Notice of intention to do the work ~~XXXX~~ (was not) submitted on Form C-102 on _____, 19_____,
(Cross out incorrect words)

and approval of the proposed plan ~~XXXX~~ (was not) obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

- October 26, 1954 - Spudded well
- October 27, 1954 - Set 8 5/8" at 300' w/175 sax cement circulated
- October 29, 1954 - Tested casing before and after drilling plug w/500 psi - OK
- November 4, 1954 - Set 5 1/2" at 2997' and cemented w/250 sax
- November 7, 1954 - Tested casing w/1500 psi - OK

Witnessed by A. T. Sindel, Jr.

(Name)

M. A. MACHRIS

(Company)

Engr.

(Title)

Approved:

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Representing

M. A. MACHRIS

Address

811 Midland Tower Bldg., Midland, Texas