

## NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Dalport Oil Corporation</b>				Address <b>930 Fidelity Union Life Bldg. Dallas, Texas</b>			
Lease <b>Caprock-State</b>		Well No. <b>1</b>	Unit Letter <b>M</b>	Section <b>30</b>	Township <b>12S</b>	Range <b>32E</b>	
Date Work Performed <b>5-20-62</b>		Pool <b>Caprock Queen</b>			County <b>Lea</b>		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
- ☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Cemented 1445' - 7" - 20# casing w/250 sx cement. Circulated 10-15 bbls cement.

Tested with cable tools. Bailed hole dry 5-22-62

Witnessed by <b>Leon M. Lampert</b>	Position <b>Geologist</b>	Company <b>Dalport Oil Corporation</b>
--	------------------------------	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

## ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

## RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover:						
After Workover:						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name <b>Leon M. Lampert</b>
Title	Position <b>Geologist</b>
Date	Company <b>Dalport Oil Corporation</b>