NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS OFFICE OCC (Submit to appropriate District Office as per Commission Rule 1106) Address
930 Fidelity Union Life Bldg. Dallas, Texas Name of Company Address Dalport Oil Corporation Lease Well No. Unit Letter Section Township Range 125 32E 30 Caprock-State 1 Date Work Performed Pool County Lea 5-17-62 Caprock Queen THIS IS A REPORT OF: (Check appropriate block) ■ Beginning Drilling Operations Casing Test and Cement Job Other (Explain): Plugging Remedial Work Detailed account of work done, nature and quantity of materials used, and results obtained. Moving in rig Witnessed by Position Company Geologist Leon M. Lampert Dalport Oil Corporation FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY ORIGINAL WELL DATA D F Elev. TD PBTD Producing Interval Completion Date Tubing Diameter Oil String Diameter Tubing Depth Oil String Depth Perforated Interval(s) Open Hole Interval Producing Formation(s) RESULTS OF WORKOVER Oil Production Water Production Date of Gas Production GOR Gas Well Potential Test BPD MCFPD BPD Cubic feet/Bbl MCFPD Before Workover After Workover I hereby certify that the information given above is true and complete to the best of my knowledge. OIL CONSERVATION COMMISSION Approved by Name Title Position Geologist Date Company Dalport Oil Corporation