

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company GRARIDGE CORPORATION			Address Box 752, Breckenridge, Texas			
Lease Caprock Unit No. 1	Well No. 32-10	Unit Letter J	Section 32	Township 12S	Range 32E	
Date Work Performed October 1958	Pool Caprock Queen			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain):
☐ Plugging ☐ Remedial Work **Convert to Injection Well.**

Detailed account of work done, nature and quantity of materials used, and results obtained.

Ran log and caliper survey. T. D. 3038 feet. Plugged back to 3020 feet with gravel and 2 sacks of cement as plug. Tested plug O.K. Cemented 46.6' of 4½" liner with 75 sacks. Top liner at 2973.4' bottom at 3020'. Drilled and cleaned out to 3038'. Well took water by gravity.

1-12-59 Began injecting water into open hole.

Witnessed by Paul Holloway	Position Superintendent	Company Graridge Corporation
--------------------------------------	-----------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. 4373'	T D 3038'	P BTD	Producing Interval 3020-3038'	Completion Date 10-14-58
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	

Perforated Interval(s)


Open Hole Interval 3020-3038'	Producing Formation(s) 3020-3038' (Injection)
---	---

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name (S. H. Lindley, Jr.)
Title	Position Engineer
Date	Company Graridge Corporation