

COPY

Form C-103
(Revised 3-55)NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY AZTEC OIL & GAS COMPANY Box 247 Hobbs, New Mexico
(Address)LEASE State LW WELL NO. 2 UNIT A S 2 T 10S R 33EDATE WORK PERFORMED 8-31-57 POOL Lane-WolfcampThis is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off☐ Beginning Drilling Operations☐ Remedial Work☐ Plugging☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

A 7-7/8" hole was drilled to 9650' and 5 1/2" OD 17 1/2" N-80 casing was cemented at 9849' using 350 sacks of Inferno cement with 2 bags of gel added. Cement was allowed to set 96 hours before resuming operations. The casing and cement job was pressure tested with 3000 psi and found to be ok. The top of cement outside the casing was found to be at 8210' by temperature survey.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test _____

Oil Production, bbls. per day _____

Gas Production, Mcf per day _____

Water Production, bbls. per day _____

Gas-Oil Ratio, cu. ft. per bbl. _____

Gas Well Potential, Mcf per day _____

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Signed By

Name _____

P. R. WATTS, JR.

Position _____

Prentice B. Watts, Jr.
District Superintendent

Company _____

AZTEC OIL & GAS COMPANY

Name _____

Title _____

Date _____



LTR



Job separation sheet

Form 1-113

Revised 1-1-61

Page 1

Case No. 100

COMMITTEE ON ASSASSINATIONS

Box 247

Albuquerque, New Mexico

REAS: State 1100

2

100

100-332

100-332

100-332

100-332

This is a copy of

x

100-332

Detailed description

100-332

A 12 " & 11" hole was drilled in the ground at 300' depth. 300' of 4-55 non-bleed casing cemented at 300' and 100' of 4-55 cement was placed. 100 sacks of regular cement with a water/cement ratio of 0.45 was placed. Cement was circulated to the surface. On the surface, all water to 100' before running operations. The casing was tested to 1000 psi for thirty minutes and found to be o.k.

FILED

Original

for file

File

Page

100-332

100-332

100-332

100-332

100-332

100-332

100-332

100-332

100-332

100-332

100-332

DATE

TIME

BY

Original Signed By

P. R. WARD

District Attorney

State of New Mexico