

HUMBLE OIL & REFINING COMPANY
HUMBLE DIVISION

P. O. Box 2347
Hobbs, New Mexico

Tabulation of all deviation
Test run on New Mexico State BQ #1
Unit 1 Section 26 Township 10-S, Range 33-E, Lea, County, New Mexico

Depth	Degrees of Deviation
850	1/2
1410	1/2
1974	3/4
3317	1/2
3787	1/2
4040	3/4
4302	1/4
4568	1
4910	1-1/4
5168	1-1/2
5453	2
5970	3/4
6187	1/4
6748	1
7022	1
7308	3/4
8431	3/4
8526	1/4
8667	3/4
8753	3/4
8875	1/4
9156	1/2
9490	1
9887	1

DRILL STEM TEST

Date: 9-13-61
Type of Test, Open Hole or Perf Csg: Open Hole
Formation Tested: From 9706 to 9745
Size Choke: Top - 1/2", Bottom - 5/8"
Tool Open: 150 min.
Formation Pressure: Flowing - 2,588, Shut In - 3,258
Recovery - Feet: Oil - 34*, Water - 22*, Other - 10.0**
Was Test Satisfactory: Yes

* reversed out (measured in barrels)
** water blanket