

## NEW MEXICO OIL CONSERVATION COMMISSION

## MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per instructions on R-20-1-51)

COMPANY Amerada Petroleum Corporation - Roswell Star Route - Tatum, New Mexico  
(Address)LEASE State B.T."P" WELL NO 1 UNQ E S 34 T 11-S R 33EDATE WORK PERFORMED 12-28-58 to 1-17-59 POOL Undesignated

This is a Report of: (Check appropriate block)

☐ Beginning Drilling Operations☐ Plugging☐ Results of Test of Casing Shut-off☐ Remedial Work☐ As Below

Detailed account of work done, nature and quantity of materials used and results obtained.

After 5-1/2" Casing Liner run Set @ 9919' W/Top of 5-1/2" Liner @ 3668 W/Brown Type "C" Casing Hanger & Type C.R. Packer set @ 3668'. After 5-1/2" Casing perforated from 9887' to 9904' & Acidized W/500 Gallons Acid. Swabbed for 18-1/2 hrs. Tested 9-5/8" Casing in top of 5-1/2" Liner Hanger W/1000#, Casing bled to 700# in 3 min. Ran Baker Bridge plug to 9850' & Dumped 1 Sx. Cement on top of Plug. Squashed top of 5-1/2" Liner W/100 Sx. Regular Cement Max PP 3600# Min 1700#. Pumped 75 sx thru top of 5-1/2" Liner & left 25 sx in 9-5/8" Casing. Drlg. Cement from 3588' to 3666' to top 5-1/2" Casing Liner. Tested Liner Hanger W/1600# Bled down to 1350# Immediately. Drilled Cement in 5-1/2" Casing & Stuck Tubing @ 4360'. Backed off Tbg @ 4258' Leaving 1 jt 2-3/8" OD Tbg & 2-3-1/2" DC & Bit in Hole. While Fishing for above Drill Pipe & Drill Collars Left 2/3 of Grapple off Spear in Hole. Fished W/Magnetic Basket W/No Recovery. Run Klustrite Shoe With Wash over pipe & Washed over fish. Trip in W/Overshot & Recovered part of Grapple off Spear. Recovered 1 jt 2-3/8" OD Tbg. Attempted to Recover 3-1/2" DP No Results. Ran Klustrite shoe & Wash over pipe & Washed over fish. Could not Pull. Ran Klustrite shoe & Wash over pipe & Milled around top of Liner Hanger. & over 5-1/2" Casing Recovered All junk left in Hole & Pulled 1690' 5-1/2" 15.5# Casing Leaving top of 5-1/2" Casing

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY @ 5371' Casing had been parted W/Some jts twisted around fish. Was unable to get over or in 5-1/2" Casing @ 5371'. Spotted Cement Plug from 5022' to 5220' W/Whip stock.

Original Well Data TO PBD Prod. Int. Comp. Date

Tbng Dia. Tbng Depth Oil String Dia. Oil String Depth

Perf Interval (s)

Open Hole Interval Producing Formation (s)

## RESULTS OF WORKOVER:

BEFORE AFTER

Date of Test

Oil Production, bbls per day

Gas Production, Mcf per day

Water Production, bbls per day

Gas Oil Ratio, cu. ft. per bbl

Gas Well Potential, Mcf per day

Witnessed by

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Title

Date

Name

Position foreman

Company Amerada Petroleum Corporation

Roswell Star Route

Tatum, New Mexico