

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410OIL CONSERVATION DIVISION
2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO. 30-025-01019
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-1347
7. Lease Name or Unit Agreement Name State BT "C"
8. Well No. 5
9. Pool name or Wildcat Bagley Penn (03770)
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4237 GL 4250 DF

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Collins & Ware, Inc.
3. Address of Operator 508 West Wall, Suite 1200, Midland, Texas 79701	4. Well Location Unit Letter <u>K</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>11S</u> Range <u>33E</u> NMPM <u>Lea</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4237 GL 4250 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Change well from TA'd status to active <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

April 1977 Well was put on temporarily abandoned status.

4/17/97 MIRU well service unit.

4/19/97 GIH with 282 joints 2 3/8" L-80 8rd tubing with turned down collars. Tag TD at 9023' without KB.

4/21/97 Re-ran crossover, SSN, and 2 3/8" 4.7# tubing and set at 9010'. Started swabbing.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Dianne Sumrall TITLE Production Supervisor DATE 5/6/97

TYPE OR PRINT NAME Dianne Sumrall TELEPHONE NO. (915) 687-3435

(This space for State Use)

APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON TITLE ASSISTANT SUPERVISOR DATE 5/6/97

CONDITIONS OF APPROVAL, IF ANY: