

## OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS REPORTS ON WELLS

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL		REPORT ON SETTING CASING	<b>X</b>

November 25, 1949

Monument, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,  
SANTA FE, NEW MEXICO  
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the \_\_\_\_\_  
**Amerada Petroleum Corporation** **State STD** Well No. **2** in the \_\_\_\_\_

Company or Operator **C/NW/4 SE/4** of Sec. **35**, T. **11-S**, R. **33-E**, N. M. P. M.,  
**Wildcat** Field, **Lea** County.

The dates of this work were as follows: **November 24, 1949**

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on **November 23,** 19 **49**  
and approval of the proposed plan was ~~obtained~~ obtained. (Cross out incorrect words.)

## DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

**3840' - Total Depth - Line. Attempted to run Schlumberger - failed to go. Ran 90 Jts., 3849.22', threads off measurement, 8-5/8" O.D., 32#, 8-Rd. Thd., Grade J-55, Range 3, S. S. New Casing - set at 3840'. Cemented with 1000 Sacks Long Horn Regular, 450 sacks ElTero Regular and 50 sacks Incon Cement. Total of 1500 sacks cement. Plug to 3750' at 8:30 A.M., 11-24-49. Maximum pump pressure 1200#.**

Witnessed by **C. E. Telge** **Amerada Petroleum Corporation** **Farm Boss**  
Name Company Title

Subscribed and sworn before me this \_\_\_\_\_

**25th** day of **November** 19 **49**

**Notary Public**

I hereby swear or affirm that the information given above is true and correct.

Name \_\_\_\_\_

Position **Assistant District Superintendent**

Representing **Amerada Petroleum Corporation**

Company or Operator

My commission expires **10/24/53**

Address **Drawer D, Monument, New Mexico**

Remarks:

**Ray, J. J. J.**  
Name  
Title

1. The first step in the process is to identify the problem or issue that needs to be addressed. This involves gathering information and understanding the context of the problem.


 The logo consists of a stylized, abstract shape that resembles a lowercase 'e' or a similar letter, enclosed within a circular border.

1. *Journal of the American Medical Association*, 1990; 263: 1025-1026.

• **Prevalence** is the proportion of a population that has a disease at a particular point in time.

1990

Handwritten signature: *Handwritten signature*