

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease

State ☒ Fee ☐

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name State BD
3. Address of Operator P. O. Box 1861, Midland, Texas 79702	9. Well No. No. 1
4. Location of Well UNIT LETTER H 1980 North 660 FEET FROM THE LINE AND FEET FROM East 2 12-S 33-E THE LINE, SECTION TOWNSHIP RANGE NMPM.	10. Field and Pool, or Wildcat Bagley Siluro Dev.
11. Elevation (Show whether DF, RT, GR, etc.) 4243' D.F.	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

Case #4887, Order #R-4460

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRU. Started to bleed well down, attempt was unsuccessful. Left well flowing into frac tank, 1" opening for 14 hours, well flowed 25 BO, 20# TP. Killed well with 130 bbls lease water, circ 130 BO to frac tank. Install BOP. Jarred on pkr 2 hrs to release. POH and laid down 63 jts of 2-3/8" tbg.

Finished laid down of 2-3/8" tbg and KOBE csg pump pkr. Picked up 2500 of 2-3/8" tbg, 7" csg scraper and bit. RIH w/rest of tbg to 10,400'. POH w/tbg, bit & scraper. RIH w/Model R pkr to 3000'. Finish RIH w/tbg to 10,400, pkr seat. Repair swab line. Chg out swab line. Swab 3 hrs, end 4:30 pm. Rec'd 48 BO, 1 BW, FL 200-2100', swb 7-1/2 hrs, rec'd 9 BO, 101 BLW, FL 2000-2800' and steady, no gas. (-29 BLW). Swb'd 7 hrs, rec'd 6 BO, 29 BLW, 74 BFW, FL 2100' to 2800', no gas show, unseat pkr, POH, lay down 4500' 2-7/8" tbg, RIH w/pmp set up. TS 6026, PN 5996', SN 5995', TAC 5992', ran 86 taper rod string, 1-3/4" pump, stg, RR 7:30.

Set up PU (start up), Com unit & eng. 19 hrs 78 BO/32 BW 9 x 144 x 1-3/4 21/BO & 2 BW, SD to install belt guards, 24 hrs 42 BO/320 BW, 24 hrs 50 BO/336 BW on 12-1-81

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Maria L. Perez TITLE Sr. Accounting Assistant DATE December 3, 1981

APPROVED BY [Signature] TITLE [Signature] DATE 12-7-1981

CONDITIONS OF APPROVAL, IF ANY: