

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Skelly Oil Company Box 38 Hobbs, New Mexico
(Address)

LEASE Blue Quail Unit WELL NO. 1 UNIT "N" S 19 T 10S R 34E
DATE WORK PERFORMED March 7 & 8, 1958 POOL Wildcat

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☒ Plugging ☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Well plugged and abandoned as follows:

The 13-3/8"OD casing was set at 350' and cemented to surface with 370 sacks. The 9-5/8"OD casing was set at 4120' and cemented with 2000 sacks. Spotted 100 sacks cement 13,270-13,000'. Filled with heavy mud laden fluid to 10,450'. Spotted 100 sacks cement 10,150-10,450'. Filled with heavy mud laden fluid to 5600'. Spotted 75 sacks cement 5400-5600'. Filled with heavy mud laden fluid to 4100'. Spotted 50 sacks cement 3950-4100'. Filled to surface with heavy mud laden fluid. Ran 10 sacks cement for cap and installed 4" pipe marker. Well plugged and abandoned March 8, 1958.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____
Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____
Perf Interval (s) _____
Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

	BEFORE	AFTER
Date of Test	_____	_____
Oil Production, bbls. per day	_____	_____
Gas Production, Mcf per day	_____	_____
Water Production, bbls. per day	_____	_____
Gas-Oil Ratio, cu. ft. per bbl.	_____	_____
Gas Well Potential, Mcf per day	_____	_____
Witnessed by _____		

(Company)

OIL CONSERVATION COMMISSION

Name John W. Kunyan
Title _____
Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name John W. Kunyan
Position District Superintendent
Company Skelly Oil Company