



(SUBMIT IN TRIPLICATE)

L Office _____

UNITED STATES OFFICE O. C. C.
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLease No. 10,000,000
Unit Production

MAR 13 9 17 AM '66

A-6

Bought Field

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 13,

1966

Well No. 1 is located 660 ft. from N line and 3000 ft. from E line of sec. 10
10/4 Sec. 10 90 250 1000
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Ida New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 1226 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 7" Cas 1725' w/100lb/ft Cement casing. Packed and recovered 53 Jcs, 1007' of 7", 2-55, Cas. Set of 25 dia cement plug thru 2" Cas in 7" Cas 1725-1750' & in 9 5/8" Cas 1715-1690'. Set 10 dia cement plug 25-50'. Put latex fluid between plugs. Install 10000 cement. Plugging Completed 12-27-60.

Location cleaned and ready for inspection March 8, 1966.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Security Mobil Oil Company, Inc.Address P.O. 2406, Hobbs, New Mexico

By _____

Title District Superintendent