NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

	of the Commission. Indicate Nature of Report by Checking Bo	Plow	
	Indicate Nature of Report by Checking Be	510W	
EPORT ON BEGINNING RILLING OPERATIONS	REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL	
EPORT ON RESULT F PLUGGING WELL	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)	
	May 11,1955.	Hobbs, Lew Mexico	
Following is a report on the work of	(Date)		Place)
	nin do oration Stat		
(Company or Open	ator)	(Lease)	20
McVay & Stafford (Contractor)	, Well No	in the G 1/4 SV 1/4	of Sec29
.11-5, R3.5-E, NMPM.,	ildcat Pool,	Leu	County.
he Dates of this work were as folows:	eay 3,1955		
otice of intention to do the work (was)	(**X**********************************	(Cross sure incorrect words)	, 19,
nd approval of the proposed plan (was)	(man mat) abtained	20 4 th	
nd approvar of the proposed plan (was)	(was not) obtained.	·4i,	
D.10088. Hole was f	ED ACCOUNT OF WORK DONE AND RESI	fluid. 50 Sacks ce 6 4218. 50' Plug pl	
D.10088. Hole was f	illed with heavy mud laden 9956. 35 Sacks from 4310 to	fluid. 50 Sacks ce 6 4218. 50' Plug pl	
DETAIL .B.10088. Hole was find the bound of	illed with heavy mud laden 9956. 35 Sacks from 4310 to	fluid. 50 Sacks ce 6 4218. 50' Plug pl	
DETAIL D.10088. Hole was find the state of the bound of the state of the bound of	illed with heavy mud laden 9956. 35 Sacks from 4310 to	fluid. 50 Sacks ce 6 4218. 50' Plug pl	
DETAIL D.10088. Hole was figoreted from 10088 to figoretellar f 9 5/8 Casing. Cellar	illed with heavy mud laden 9956. 35 Sacks from 4310 to	fluid. 50 Sacks ce 6 4218. 50' Plug pl	
DETAIL D.10088. Hole was find the state of the potted from 10088 to f 9 5/8 Casing. Cellar	illed with heavy mud laden 9956. 35 Sacks from 4310 to	fluid. 50 Sacks ce 6 4218. 50' Plug pl	
DETAIL D.10088. Hole was find the second of 10088 to find 10088 to find 5/8 Casing. Cella laced over well bore.	illed with heavy mud laden 9956. 35 Sacks from 4310 to r filled, Location levelled	fluid. 50 Sacks ce 4218. 50' Plug pl and regulation man	rk er
DETAIL D.10088. Hole was figotted from 10088 to f 9 5/8 Casing. Cella laced over well bore.	ED ACCOUNT OF WORK DONE AND REST	fluid. 50 Sacks ce 2 4218. 50' Plug pl and regulation man	rk er
DETAIL D.10088. Hole was from 10088 to food from 10088 to food food food food food food food f	illed with heavy mud laden 9956. 35 Sacks from 4310 to r filled, Location levelled -Continent Petroleum Coro.	fluid. 50 Sacks ce 4218. 50' Plug pland regulation man	an
DETAIL D.10088. Hole was fine potted from 10088 to f 9 5/8 Casing. Cella laced over well bore. Witnessed by O.T.Owen Name (Name)	illed with heavy mud laden 9956. 35 Sacks from 4310 to r filled, Location levelled -Continent Petroleum Coro.	fluid. 50 Sacks ce 4218. 50' Plug pland regulation man	an
DETAIL D.10088. Hole was find the state of	illed with heavy mud laden 9956. 35 Sacks from 4310 to r filled, Location levelled Continent Petroleum Corp. (Company) I hereby certify to the best of the best	fluid. 50 Sacks ce 4218. 50' Plug pland regulation man	an