U.S.G.S. LAND OFFICE OPERATOR SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65 Sa. Indicate Type of Lease State E Fee. 5. State Oil & Gas Lease No. E-6915
U.S.G.S	State X Fee
1. OIL CAS WELL OTHER- 2. Name of Operator The Atlantic Refining Company 3. Address of Operator P. O. Box 1978, Roswell, New Mexico 4. Location of Well UNIT LETTER N 66C FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP SRANGE 36-E. NMPM. LINE, SECTION 2 TOWNSHIP SRANGE 36-E. NMPM.	
OIL GAS WELL OTHER- 2. Name of Operator The Atlantic Refining Company 3. Address of Operator P. O. Box 1978, Roswell, New Nexico 4. Location of Well UNIT LETTER N 66C FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP SRANGE 36-E, NMPM. 15. Flevention (Show whether DF, RT, GR, etc.)	7. Unit Agreement Name
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 4. Location of Well UNIT LETTER N 66C FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 9-S RANGE 36-E. NMPM. 15. Elevation (Show whether DF, RT, GR, etc.)	8. Farm or Lease Name State "AD"
UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 2 TOWNSHIP 9-S RANGE 36-E NMPM.	9. Well No.
15 Elevation (Show whether DF, RT, GR, etc.)	Allison-Abo
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4062 DF	Lea
Check Appropriate Box To Indicate Nature of Notice, Report or Oth NOTICE OF INTENTION TO:	REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK Image: commence drilling opns.   TEMPORARILY ABANDON COMMENCE DRILLING OPNS. Image: commence drilling opns.   PULL OR ALTER CASING CHANGE PLANS CASING TEST AND CEMENT JOB	ALTERING CASING Plug and abandonment <b>X</b>
OTHER	

This well was plugged and abandoned using the following procedure. Nork was begun 12/29/64. A cast iron bridge plug was set at 8960<sup>1</sup>. A common cement plug was dumped from 8940<sup>1</sup> to 8960<sup>1</sup>. 5-1/2<sup>n</sup> casing was shot off at 4300<sup>1</sup> (100<sup>1</sup> below 9-5/8<sup>n</sup> casing) and pulled. A 50 sk common cement plug was spotted from 4170<sup>1</sup> to 4350<sup>1</sup>. A 10 sk common cement plug was set from 15<sup>1</sup> to 45<sup>1</sup>, and a standard dry hole marker was installed. 8.84/gal. native gel mud was left between all plugs. Job complete 1/9/65.

0

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED_ alkeadin	TITLE Dist. Drlg. & Prod. Supt.	DATE 1-27-65
APPROVED BY JCALL CALL		NOV 10 1965

CONDITIONS OF APPROVAL, IF ANY: