For	m 9-1 eb. 19	381 a 61)			
		, .			17.10
y. 5.	3 - 1	7,546	vey.	H50	le Olsteid
				<u> </u>]

(SUBMIT IN TRIPLICATE)

	_		 -
Land Off	ice	FER	 B

Lease No. LC-067771

UNITED STATES

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Whitehall Oil Company, 1950 FEBING. #1 Beddick1

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING. SUBSEQUENT REPORT OF ALTERING CASING. SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR. SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY
-------------------------------------	---

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

(IMDIONIE)	January 19 , 1960
	January
W.II No. 1 is located	1.183.0ft. from \{\frac{\mathbb{M}}{\mathbb{S}}\}\] line and
Well 140.	MPM (Meridian)
(34 Sec. and Sec. No.)	(Twp.) (Range) (Meridian) (State or Territory)
Undesignated (Field)	(County or Subdivision)

The elevation of the derrick floor above sea level is 4044 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

Drilled out plug and drilled to 9811' - set 5-1/2" casing to 9811'-Casing consisted of 2045' of 17# N-80, 2915' of 17# J-55 and 4851' of 15.5# J-55. Cemented w/400 sx. Posmix and 100 sx. of Nest W/Baker Guide Shoe and Float Collar. Plug down 4:00 PM, 12/14/59. Waited on casing 24 hrs. Hippled up and tested to 3000%. No drop in pressure.

I understand that this plan of work must receive approval in writing by the	Geological Survey before operations may be commenced.
I understand that this plan of work must receive approval in the state of the state	
Company Whitehall Oil Company, Inc.	-
Address 1814 Mercantile Bank Building	- Dana B. Weale
Dallas 1, Texas	By Since B) lea Ce Trile Office in magor
	GPO 8620