| | | Form C-103 |
|--|---|---|
| NO. (F COPIES RECEIVED | | Supersedes Old |
| DISTRIBUTION | | C-102 and C-103 Effective 1-1-65 |
| SANTA FE | NEW MEXICO OIL CONSERVATION COMMISSION | |
| FILE | | 5a. Indicate Type of Lease |
| U.S.G.S. | | State Fee X |
| LANE OFFICE | | 5. State Oil & Gas Lease No. |
| OPEFATOR | | _ |
| ······································ | DRY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.) | 7. Unit Agreement Name |
| | | - |
| O'L GAS WELL | OTHER- | 8. Farm or Lease Name |
| 2. Man e of Operator TEXACO Inc. | | U. D. Sawyer |
| | | 9. Well No. |
| P. 0. Box 728 Hobbs, New Mexico 88240 | | 1 |
| | | 10. Field and Pool, or Wildcat |
| 4. Location of Well | 660 FEET FROM THE NOTTH LINE AND 660 FEET FR | Crossroad (Devonian) |
| | | |
| East Line, sec | TION TOWNSHIP PANGE 36-E | *************************************** |
| | 15. Elevation (Show whether DF, RT, GR, etc.) 4020' (DF) | 12. County Lea |
| | k Appropriate Box To Indicate Nature of Notice, Report or O | other Data |
| | INTENTION TO: | NT REPORT OF: |
| PERF JRM REMEDIAL WORK | PLUG AND ABANDON REMEDIAL WORK | ALTERING CASING |
| 0"HER | L | |
| | (Church state all partinent details and give pertinent dates, includ | |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, uork) SEE RULE 1103.

THE FOLLOWING WORK HAS BEEN COMPLETED ON SUBJECT WELL:

- KIII well 1.
- Pump 500 bbls 10# brine down 9-5/8" & 5-1/2" 0.D. Casing. Spotted From-Seal temporary 2. blocking agent across Devonian perforations 12,1261-12,1501. Tested to 600#. Tested 0.K.
- Pull 3-1/2" O.D. tubing & Reda pump. 3.
- Set RBP @ 7000' & 11,500'. Tested w/800# for 30 minutes. Tested 0.K. Re-set BP @ 4350' 4. and tested.
- Perforate 5-1/2" O.D. casing w/l-shot @ 4160'. Ran RTTS packer and set @ 3930'. Squeeze 5. perf. @ 4160' w/100 sx Class "C" Neat Cement.
- Ran bit & clean hole to 4185'. Test casing w/800#. Tested O.K. 6.
- Pull RBP & ran Reda Pump. 7.
- Pump 40 bbls lease crude & 170 bbls kerosene down casing. Pressure up. Clean out perfs. 8.
- Test & return well to production. 9.

| 18. hereby certify that the information above is true and complete to the best of my knowledge and belief. | | | | | |
|--|---|----------------|---------|--|--|
| SIGNED 2200 | Assistant TITLE <u>District Superintendent</u> | DATE AUGUST 12 | 2, 1969 | | |
| APPI OVED BY John w. Rungan | тітье | DATÉ | | | |
| CONDITIONS OF APPROVAL, IF ANY: | | | | | |