

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-9676-5	
7. Unit Agreement Name	
8. Farm or Lease Name	
Livermore "G"	
9. Well No.	
9	
10. Field and Pool, or Wildcat	
Caprock Wolfcamp	
12. County	
Lea	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator	3. Address of Operator	4. Location of Well
	American Petrofina Company of Texas	Box 1311, Big Spring, Texas 79720	UNIT LETTER C, 467 FEET FROM THE North LINE AND 1787 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 12-S RANGE 12-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)			
4396 DF			

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3-27-67 Spotted 35 Sx plug to 8148
3-28-67 Loaded hole w/ 10# mud
3-31-67 Shot 4 1/2" csg. @ 6700 Shot 4 1/2" csg. @ 4221
4-1-67 Recovered 4241' of 4 1/2" csg. Spotted 25 Sx in and out of 4 1/2" Stub @ 4221. Spotted 25 Sx in and out of intermediate csg. @ 3736. Loaded hole w/ 10# mud.
4-2-67 Shot 8 5/8" csg. @ 447. Shot 8 5/8" csg. @ 414. Recovered 408' of 8 5/8" csg. Spotted 40 Sx plug in and out of 8 5/8" stub @ 414. Spotted 10 Sx @ Surface Installed marker. P&A 4-2-67 Lease is cleaned up and ready for inspection.
Csg. left in hole: 4 1/2" 4240-12,036 8 5/8" 414-3736 13 3/8 0-373

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.M. Denson TITLE Asst. District Mgr. of Prod.

DATE 5/12/67

APPROVED BY

John W. Runyan

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: