

Wilson Energy, Inc.
Activity Report
New Mexico State "I" No. 1
660' FNL & 1970.0 FEL (B)
Sec. 7, T-11-S, R-34 E
Lea County, New Mexico
Inbe Bough "C" Formation

7/20/88 - Co TD 8674' - Jar loose from fish POOH - Rec. Pc.
Junk Iron - TIBH - Latch on to fish @ 8655' - Wash
& Circ. to 8674' Jar on fish - Circ Hole clean &
SD.

8/02/88 - TD 8674 - Fish @ 8655' - Work Fish & Jar - Have 20'
Free Movement - Parted TBG @ 6815' - POOH - Had
Jumped Pin TIH w/Center Spear & Latch on to Fish
Jar on Fish - worked loose tool joints - POOH &
Tighten Jts. - TBIH & Circ Clean.

8/22/88 - Jar on Fish - POOH - Lay Dn Spear - Rec. 4 Pcs.
sucker rod & Junk Iron - SBIH - Ran 1900' TBG - SD
Rain.