

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 12 9 50 AM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
OG-202

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator PAN AMERICAN PETROLEUM CORPORATION	8. Farm or Lease Name STATE "DH"
3. Address of Operator BOX 68, HOBBS, N. M. 88240	9. Well No. 1
4. Location of Well UNIT LETTER I 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE EAST LINE, SECTION 21 TOWNSHIP 11-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat BAGLEY, No. Lower Res.
15. Elevation (Show whether DF, RT, GR, etc.) 4278' R.D.B.	12. County LEA

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In an effort to increase productivity remedial work performed as follows:

Perforated interval 9750-60' w/ 2JSPF. Acidized and perfs 9750'-9959' w/ 3000 gal 15%. Evaluated.

Prior - Pmp. 187 BOX 141 B7H, 24 hrs.
After - 163 BOX 35 B7H, 24 hrs.
Unsuccessful Workover.

TD - 10 130'
PBD - 10 090'
5 1/2" CSA 10 130'

DEEPS:
9750-59, 9912-24, 42-59

OC - 5-8-69
COMP - 5-22-69

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Area Engr	DATE 6-11-69
APPROVED BY John W. Runyan	TITLE Geologist	DATE JUN 11 1969
CONDITIONS OF APPROVAL, IF ANY: 1-RR		