

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/></p> <p>5. State Oil & Gas Lease No.</p>
<p>1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/></p> <p>2. Name of Operator Gulf Oil Corporation</p> <p>3. Address of Operator Box 670, Hobbs, New Mexico 88240</p> <p>4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 13 TOWNSHIP 11-S RANGE 33-E NMPM.</p>		<p>7. Unit Agreement Name</p> <p>8. Farm or Lease Name Mary Wilson</p> <p>9. Well No. 1</p> <p>10. Field and Pool, or Wildcat Inbe Penn</p>
<p>15. Elevation (Show whether DF, RT, CR, etc.) 4215' GL</p>		<p>12. County Lea</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

Plugged and Abandoned

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9900' TD.

Pulled tubing. Set CI BP at 7750' and capped with 3-1/2 sacks of cement. Loaded hole with heavy mud. Cut and recovered 5-1/2" casing from 3950'. Spotted 20 sack cement plug from 3900' to 4,000', across 5-1/2" stub at 3950' and across 8-5/8" shoe at 3987'. Spotted 12 sack cement plug from 62' to surface. Installed dry hole marker. Plugged and abandoned September 20, 1971. Will advise when location is ready for your final inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ORIGINAL SIGNED BY
C. F. KALTEYER

SIGNED **C. F. KALTEYER** TITLE **Area Engineer**

DATE **September 20, 1971**

OIL & GAS INSPECTOR

APPROVED BY **Nathan E. Clegg**
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

JAN 22 1972

RECEIVED

SEP 27 1971

**OIL CONSERVATION COMM.
HOBBS, N. M.**