| NO. OF COPIES RECEIVED  |   | Form C-103  |
|---|---|---|
| DISTRIBUTION  |   | Supersedes Old<br>C-102 and C-103   |
| SANTA FE  | NEW MEXICO OIL CONSERVATION COMMISSION  | Effective 1-1-65  |
| FILE  |   |   |
| U.S.G.S.  |   | 5a. Indicate Type of Lease  |
| LAND OFFICE   |   | State 🗶 Fee.  |
|   |   | 5. State Oil & Gas Lease No.  |
| OPERATOR  |   | K-4601  |
|   | DAY MOTIOTO AND DEPONTS ON WELLS  |   |
| OD NOT USE THIS FORM FOR P<br>USE "APPLICA"   | RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT _" (FORM C-101) FOR SUCH PROPOSALS.)   |   |
| OIL GAS WELL WELL   | OTHER-  | 7. Unit Agreement Name  |
| 2. Name of Operator   | UTILITY .   | 8. Farm or Lease Name   |
|   | Company   | Shell-State   |
| Western Equipment 3. Address of Operator  | Company   | 9. Well No.   |
| - •   | m B0801   | •   |
|   | dland, Texas 79701  | 10. Field and Pool, or Wildcat  |
| 4. Location of Well   |   |   |
| UNIT LETTER   | 555 FEET FROM THE <b>north</b> LINE AND 555 FEET  | TROM The (Permo-Penn.)  |
|   |   |   |
| THE West LINE, SEC  | TION 19 TOWNSHIP 11-S RANGE 34-E  | NMPM.   |
|   |   |   |
|   | 15. Elevation (Show whether DF, RT, GR, etc.)   | 12. County  |
|   | 4217' K.B.  | Lea   |
| 16. Cl1   |   |   |
|   | Appropriate Box To Indicate Nature of Notice, Report  |   |
| NOTICE OF   | INTENTION TO: SUBSEQ  | UENT REPORT OF:   |
|   |   | _   |
| PERFORM REMEDIAL WORK   | PLUG AND ABANDON X REMEDIAL WORK  | ALTERING CASING   |
| TEMPORARILY ABANDON   | COMMENCE DRILLING OPNS.   | PLUG AND ABANDONMENT  |
| PULL OR ALTER CASING  | CHANGE PLANS CASING TEST AND CEMENT JOB   |   |
| -   | OTHER   |   |
| OTHER   |   |   |
|   |   |   |
| 17. Describe Proposed or Completed work) SEE RULE 1903.   | Operations (Clearly state all pertinent details, and give pertinent dates, inc  | cluding estimated date of starting any proposed   |
| 9890' - cemented of as Bough "C" well in July, 1970 at as follows:  Run tubing to collapsed case 25 sacks ceme 25 | Incor - top cement behind 8 5/8" at 1 with 525 sacks Incor - top of cement a in June, 1967 by perforating 9814-31'7750'. Unable to repair collapsed cas o 7650' - attempt to pump 100 sacks cesing at 7750'. ent at 5½" stub estimated at 5000'. ent at 8 5/8" shoe at 3972'. ent at 8 5/8" stub estimated at 1200'. ent at 11 3/4" shoe at 370'. ent in top of 11 3/4" casing. | nt 6050". Completed<br>. 5½" casing collapsed<br>sing. Propose to P&A<br>ement below 7650' throug |
|   |   |   |
| •   |   |   |
| 18. I hereby certify that the informat  | ion above is true and complete to the best of my knowledge and belief.  |   |
| -   | ~ ·   |   |
| BAN   | Ph. 4   | DATE 9-8-70   |
| SIGNED  | TITLE / (Color) bo  |   |
| 1100  |   |   |
| Vollati   | A MARKET  | 0.4.4070  |
| APPROVED BY   | Mill TITLE  | PATE  |
| CONDITIONS OF APPROVAL, IF  | NY:   | . <b>L</b>  |
|   |   |   |