NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NO. DE COPIES RECEIVED		Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION	
FILE		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Fee X
OPERATOR		5, State Cil & Gas Lease No.
O. EKKTOK		
		mmmmmmm
SUNDA	RY NOTICES AND REPORTS ON WELLS  OPPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  TION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
	ION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)	
l. OIL GAS		7. Unit Agreement Name
WELL WELL	other. Abandoned oil well	
2. Name of Operator		8. Farm or Lease Name
Allen K. Trobaugh		Wood
3. Address of Operator		9. Well No.
106 Wall	Towers West, Midland, Texas 79701	2
4. Location of Well	The second secon	10. Field and Pool, or Wildcat
	1980 wost 660	Vada Penn
UNIT LETTER	1980 FEET FROM THE West LINE AND 660 FEET FROM	THE THE THE THE THE
	00	
THE NORTH LINE, SECTION	ON 29 TOWNSHIP 9S RANGE 34E NMPM.	
		<u> </u>
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4283 GR	Lea (((((()))))
16. Check	Appropriate Box To Indicate Nature of Notice, Report or Ot	has Dava
		•
NOTICE OF IN	NTENTION TO: SUBSEQUEN	T REPORT OF:
L1		1
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
17. Describe Proposed or Completed Op	perations (Clearly state all pertinent details, and give pertinent dates, including	estimated date of starting any proposed
work) SEE RULE 1103.		
9/3/76-9/18/76:		
	n Basin Casing Pullers, Inc. unit. Set	CIDD A GOOG!
		CIBP @ 9000
w/20' (2 sax) c	mt plug on top.	
2. Shot 5½" casing @ 7994', 5883', 5503. Unable to work loose. Shot off		
@ 5017' and pulled 5023.51' (128 jts) casing.		
3. Ran tubing to 5	050'. Loaded hole w/brine water & salt g	el. Spotted 35 sack
cmt plug (100')	from 5050 to 4950'. Pulled tubing up t	o 4010' and spotted
45 sack cmt plue	g (100') from 4010' to 3910'.	Transportation of the state of
	ing @ 1203'. Unable to work loose. Shot	off @ 1120! and
pulled 1117.72'		OII 6 IIAO dilu
J. Loaded Hote W/D	rine and salt gel and spotted 50 sack cm	ic bind (117.) trow
11/0 to 1058',	75 sack cmt plug (203') from 414 to 211'	•
6. 10 sack plug @		
7. Installed dry he		
8. Casing left in v	well: 364' 12 3/4"; 2889.34' 8 5/8"; 489	8.87' 55"
	still on location. Pits not filled, loca	
1 1 1 - 1		.c.o. noc icverieu.
18. I herehy certify that the information	above is trite and complete to the hest of my knowledge and hatiaf	
18. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.	
(1.2.1 1/N/I		
19. I hereby certify that the information	above is true and complete to the best of my knowledge and belief.  Operator	DATE 9/28/76
(ind 1/\/)	Thang Derator	
(ind 1/\/)	Thang Derator	
(1.24 1/N/I	Operator  OIL & GAS INSPECTOR	
(1.2.1 1/N/I	Operator  Old & GAS INSPECTOR	