

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 3 11 36 AM '68

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - A" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - <b>Dry Hole</b>	7. Unit Agreement Name
2. Name of Operator <b>The Superior Oil Company</b>	8. Farm or Lease Name <b>Hutcherson "A" COM</b>
3. Address of Operator <b>P. O. Box 1900, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>B</b> <b>1980</b> FEET FROM THE <b>East</b> LINE AND <b>660</b> FEET FROM THE <b>North</b> LINE, SECTION <b>27</b> TOWNSHIP <b>9-S</b> RANGE <b>34-E</b> NMPM.	10. Field and Pool, or Wildcat <b>Vada-Pennsylvanian</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4240 DF; 4241 KB; 4224 GL</b>	12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUS AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Shot 8-5/8" casing into at 1622, pulled and recovered casing.
- Equalized 25 sack cement plug on top of casing stub at 1612. Top of cement at 1568.
- Spotted 50 sack cement plug 424 to 335.
- Placed 10 sack plug in top of 11-3/4 surface casing.
- Cut off casing below ground level. Welded steel plate on top of casing, installed dry hole marker to extend 4' above ground level. Plugged and abandoned June 22, 1968.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. V. Sivogel* TITLE Production Engineer DATE July 1, 1968

APPROVED BY *John W. Runyan* TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: