

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG 2392

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator Coquina Oil Corporation	8. Farm or Lease Name State 36
3. Address of Operator 418 Building of the Southwest, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER N, 1980 FEET FROM THE West LINE AND 660 FEET FROM THE South LINE, SECTION 36 TOWNSHIP 10-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) GL 4206, KB 4218	12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 10-8-71 Pulled tubing, rods, pump. Set cast iron B.P. at 9018' in 5½" casing with 30' cement on top of B.P.
- 10-11-71 Shot 5½" casing at 6001' - stuck. Shot 5½" at 4000' - came free. Spotted 35 sacks Class H cement on 5½" stub at 4000'. Pulled and laid down 5½" casing. Shot 8 5/8" casing at 1121' - came free - Spotted 30 sacks Class H cement on 8 5/8" stub at 1121. Laid down 8 5/8" casing to 410' - Spotted 25 sacks Class H cement across bottom 13 3/8" casing from 330'-410'. Began pulling rest of 8 5/8" - accidentally dropped 3 JTS 8 5/3" casing into hole. Stuck in cement at 330'. Spotted 10 sacks cement in top 13 3/8" and erected DHM. P&A complete October 14, 1971. Filled with mud between plugs.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J.B. Taylor</u>	TITLE <u>Superintendent</u>	DATE <u>October 19, 1971</u>
APPROVED <u>Nathan E. O'Leary</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>DEC 22 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		