

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K 3983

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator MGF Oil Corporation	8. Farm or Lease Name Nine Ranch, Inc. State
3. Address of Operator 1126 Vaughn Building, Midland, Texas 79701	9. Well No. 5
4. Location of Well UNIT LETTER I , 1980 FEET FROM THE South LINE AND 2130 FEET FROM THE East LINE, SECTION 22 TOWNSHIP 10-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4203' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set cast iron bridge plug @ 9712', 2 sx cement on top of plug
Shot 5 1/2" casing off at 4142'
Spotted 40 sx in and out of 5 1/2" stub
Spotted 40 sx in and out of 8 5/8" shoe @ 3900'
Shot 8 5/8" casing off @ 1171'
Spotted 40 sx in and out of stub of 8 5/8" casing
Spotted 25 sx in and out of shoe of 13 3/8" @ 335'
Spotted 10 sx @ surface

Spotted 10# mud between all plugs

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *[Signature]* TITLE **Engineer** DATE **January 12, 1972**
APPROVED BY *Nathan E. Vlegg* TITLE **OIL & GAS INSPECTOR** DATE **DEC 15 1972**
CONDITIONS OF APPROVAL, IF ANY: