NUMBER OF COPIES OF CETALS  OISTHIBUTION  SANTA I I  FILE  U.E.G.S  LAND OFFICE  OTHANSPORTER  OIL  THANSPORTER  OIL  OPERATOR		EW MEXICO O MISCELLAN t to appropriate i	IEOUS REP	DRTS ON WE	ELLS	FORM C-103 (Rev 3-55)
Name of Company BTA OIL PRODUCERS  Address 104 South Pecos, Midland, Texas						land, Texas
			Letter Section	Township 10-S	R	ange 33-E
Date Work Performed Pool County 5-22; 5-28-68 Undesig. Penn Lea						
THIS IS A REPORT OF: (Check appropriate block)						
Beginning Drilling Operations  Casing Test and Cement Job  Other (Explain):  Plugging  Remedial Work						
Detailed account of work done, nature and quantity of materials used, and results obtained.						
12 3/4" OD 33-38 T & C casing @ 371' w/375 sx. cement. Cement circulated-plug down 11:30 p.m.  5-23-68 W.O.C. 19 hrs-Pressure tested 12 3/4" OD casing to 1000 psiOK.  5-27-68 Drilled 11" hole to 4009'. Cemented 8 5/8" OD, 24 & 28#  ST&C casing @ 4009' w/400 sx. cement. Plug down 4:00 p.m.  5-28-68 W.O.C. 18 hrs Pressure tested 8 5/8" OD casing to 1500 psi. OK.						
Witnessed by Bill Breed  Position Field Drlg. Supt.  Company BTA OIL PRODUCERS						
FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY						
ORIGINAL WELL DATA						
D F Elev.	D	PBTD		Producing Interv	al	Completion Date
Tubing Diameter	Tubing Depth		Oil String Diamet	er	Oil String	Depth
Perforated Interval(s)						

Open Hole Interval

Producing Formation(s)

RESULTS OF WORKOVER

Test Date of Test Oil Production BPD Gas Production BPD Gos Well Potential MCFPD Before Workover After Workover

OIL CONSERVATION COMMISSION

1,161

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by

Name

Position

Production Superintendent

Date

Title

Company
BTA OIL PRODUCERS