

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator MIDWEST OIL CORPORATION		8. Farm or Lease Name State Q
3. Address of Operator c/o Hobbs Pipe & Supply Co., Box 2010, Hobbs, N. M. 88240		9. Well No. 1
4. Location of Well UNIT LETTER D 510 FEET FROM THE West LINE AND 660 FEET FROM THE North LINE, SECTION 36 TOWNSHIP 10 RANGE 33 NMPM.		10. Field and Pool, or Wildcat Vada Penn
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set a CIBP @ 9850', dumped 35' of cement on top.
2. Loaded hole w/mud-laden fluids.
3. Spotted a 25 sx plug @ casing stub, 5400'.
4. Spotted a 35 sx plug @ base of intermediate casing shoe, 4040'.
5. Spotted a 35 sx plug @ 8-5/8 casing stub, 1000'.
6. Spotted a 35 sx plug @ base of surface casing, 335'.
7. Spotted a 10 sx plug @ top of casing, erected 4" regulation marker.
8. Well was plugged & abandoned on 5/1/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Stanley Sackin</u>	TITLE <u>AGENT</u>	DATE <u>5/2/73</u>
Orig. Signed by: <u>John Runyan</u> <u>Geologist</u>		
APPROVED BY _____	TITLE <u>Geologist</u>	DATE <u>5/2/73</u>
CONDITIONS OF APPROVAL, IF ANY:		