

DEVIATION TEST DETAIL

OPERATOR: Union Oil Company of California

CUL 11 11 AM '68
UNIT LETTER: 10

LEASE: State "12"

LOCATION OF WELL: 660' from the
South line and 660' from the West
line of Section 12, Township 10-S,
Range 33-E, Lea County, New Mexico.

WELL NO.: 1

FIELD AND POOL: Inbe Permo Penn


<u>TEST FOOTAGE</u>	<u>DEGREE</u>	<u>TEST FOOTAGE</u>	<u>DEGREE</u>
400'	3/4°	5052'	1°
1900'	1/2°	5282'	1°
1392'	1/2°	5745'	1/2°
1868'	3/4°	6148'	1/2°
2305'	1/2°	6502'	3/4°
2613'	3/4°	6920'	3/4°
3080'	3/4°	7214'	3/4°
3380'	1 1/2°	7451'	1/2°
3850'	1 1/4°	8393'	1°
3950'	3/4°	8780'	1°
4420'	3/4°	9033'	1/2°
4800'	1°	9246'	1/4°

A F F I D A V I T

Before me, the undersigned authority, personally appeared D. R. Bell, known to me to be the person whose name is subscribed hereto, whom after being duly sworn, on oath states; that he is authorized to make this detail of deviation which he states was taken from actual slope tests during the course of drilling the above mentioned well, and that the detail of deviation is true and correct.


D. R. Bell - Area Superintendent

SWORN AND SUBSCRIBED TO BEFORE ME, this the twenty-ninth day of July, 1968.


Notary in and for the County of Lea,
State of New Mexico