

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

APR 23 12 01 PM '69

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
--	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator McGrath & Smith, Inc.		8. Farm or Lease Name Wright A
3. Address of Operator 418 Building of Southwest, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER <u>B</u> , 1980 FEET FROM THE <u>E</u> LINE AND 660 FEET FROM THE <u>N</u> LINE, SECTION <u>26</u> TOWNSHIP <u>9-S</u> RANGE <u>34-E</u> NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) GL 4191 KB 4203		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran 2-3/8 Tbg. spotted 35 sx. cmt. in 5½ from 9494-9846
Cut 5½ csg. at 7991 - stuck. Cut 5½ at 6492' came free
Spotted 25 sx. cmt. 6492'
Spotted 25 sx. 5370-5445'
Spotted 25 sx. cmt. 3973-4048'
Cut 8-5/8 csg. at 1295' - spotted 25 sx. cmt. 1104-1290'. Pulled 13-3/8
Spotted 25 sx. cmt. from 345-400'
Spotted 10 sx. cmt. top of 13-3/8
Installed steel plate in top 13-3/8 and installed marker
P & A complete 6 p.m. 4-16-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. H. Taylor TITLE Engineer DATE April 21, 1969

APPROVED BY John W. Ramsey TITLE SLP DATE 4-21-69

CONDITIONS OF APPROVAL, IF ANY: