

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>OG-4542-1</b>

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator	8. Farm or Lease Name	
<b>Tri-Service Drilling Company</b>	<b>McKnight State</b>	
3. Address of Operator	9. Well No.	
<b>P. O. Box 1785 - Midland, Texas 79701</b>	<b>1</b>	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER <b>1</b> , <b>946</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>East</b> LINE, SECTION <b>6</b> TOWNSHIP <b>11S</b> RANGE <b>35E</b> NMPM.	<b>Wildcat</b>	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
<b>4157' D.F.</b>		<b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spotted 25 sks. plugs @ 13,318, 9942', 7827', 5595', 4199'. Plugs in place 11:45 p.m. 11-12-68.

Shot 9-5/8" casing to pull @ 1595', 1471', 1390', 1284', 1195' and 1081'. Recovered 1078' 9-5/8" casing. Spotted 25 sks. plug at 1081', 10 sk. plug at surface. Dry hole marker installed. Job completed 6-26-69.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>D. W. Allen</i>	TITLE <b>Prod. Supt.</b>	DATE <b>3-9-72</b>
APPROVED BY <i>Nathan E. Olegg</i>	TITLE <b>OIL &amp; GAS INSPECTOR</b>	DATE <b>MAR 15 1972</b>
CONDITIONS OF APPROVAL, IF ANY:		