

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
2. Name of Operator <b>Meadco Properties, Ltd.</b>		5. State Oil & Gas Lease No.
3. Address of Operator <b>606 Vaughn Building, Midland, Texas 79701</b>		7. Unit Agreement Name
4. Location of Well UNIT LETTER <b>L</b> <b>1980</b> FEET FROM THE <b>1980</b> LINE AND <b>South</b> <b>810</b> FEET FROM THE <b>West</b> LINE, SECTION <b>4</b> TOWNSHIP <b>12 S</b> RANGE <b>33 E</b> NMPM.		8. Farm or Lease Name <b>Shell AX State</b>
		9. Well No. <b>1</b>
		10. Field and Pool, or Wildcat <b>No. Bagley - Undesignated</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4273 GL</b>		12. County <b>Lea</b>

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOB ☒  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled 7-7/8" hole to a total depth of 10,150'.  
Ran 4-1/2", 11.6#, N-80 and J-55, LT&C casing to 10,144.00' KB.  
Cemented the casing with 500 sacks of 50/50 Incor Pozmix cement with 2% gel,  
0.75% CFR-2 and 11# salt. The plug was pumped into place at 10:40 a.m., 10-3-68.  
Waited on cement for 18 hours and tested to 2500 psig. It held okay.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED James A. Loach

TITLE Petroleum Engineer

DATE Nov. 4, 1968

APPROVED BY John W. Runyan

TITLE

DATE

CONDITION OF APPROVAL, IF ANY: