

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N M 0348788-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL ☒ GAS ☐  
WELL WELL OTHER

2. NAME OF OPERATOR

The Maurice L. Brown Company

3. ADDRESS OF OPERATOR

Suite 200/Sutton Place Bldg. Wichita, Kansas 67202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

U L "J", 1980' F S L &amp; 1980' F E L

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4141' KB

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Feather 688 Ltd.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Vada Penn

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 1

T-9-S, R-35-E

12. COUNTY OR PARISH

Lea

13. STATE

N.M.

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

## SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOT OR ACIDIZE ☐ABANDON\* ☐SHOOTING OR ACIDIZING ☐ABANDONMENT\* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) ☐

(Other)

Temporarily Abandon x

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

1-2-80 thru 2-13-80

Moved in rig to change pump, rods parted while running new pump.  
Attempted to pull tubing. Tubing was stuck in old casing collapse.  
Cut tubing above and below old collapse, jarred tubing out.  
Attempted to swedge out casing. Casing separated below collapsed area.  
Ran McCullough 3 arm caliper to 6544'. Caliper survey showed 7 1/2" hole  
from 6505' to 6512', 6 1/2" hole from 6512' to 6527' and 13" to 16" plus  
hole from 6311' to 6317'.

Rigged down unit.

Will submit application to plug and abandon in the near future.

RECEIVED

MAR 12 1980

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

W. M. Groesbeck

TITLE

District Engineer

DATE

3-4-80

(This space for Federal or State office use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAR 13 1980

ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side